		1				Time	Comme	Error	Err
	Туре	# -J	Hits	Search Text	DBs	Stamp		Defini tion	ors
					лв;	2007/0			
Н	IS&R	Γ 1	975	(385/109-113).CCLS.	USPAT;	90/6			
					EPO	09:27			
				near2 (fiber or	UB;	2007/0			
7	BRS	172	7168	fibers or fibre or fibres) near2 (cable	USPAT;	90/6			
				or cables).ti,ab.	EPO	09:28			
					UB;	2007/0		i	
m	BRS	L3	7568	1 or 2	USPAT;	90/6			
					EPO	09:59			
				(strength or reinforcement or	US-PGPUB;	0/2002			
41	BRS	L4	97120	orcing or stress) near2 (rod		90/6			
				rods or member or members or wire or wires or element or elements)		10:01			
					UB;	2007/0			
Ŋ	BRS	1.5	1645	3 and 4	USPAT;	90/6			
					EPO	10:01			
				(twisting or torsions]) nesv3 (stiffness	UB;	2007/0			
9	BRS	17e	8817	Or COLSTONAL MEALS (SCILLINGS)	USPAT;	90/6			
					EPO	10:02			
					UB;	0/2007			
7	BRS	L7	25697	(shear or elastic) near3 modulus	USPAT;	90/6			
					EPO	10:02			
					UB;	2007/0			
œ	BRS	L8	93	5 and (6 or 7)	AT;	90/6			
					EPO	10:02			

Type L	#	Hits	Search Text	DBs	Time Comme Stamp nts	Comme	Error Defini tion	Err
BRS	L1	1	((optic or optical or fiber or fibre) and cable and ((twist or twisting or torsion or torsional) near3 (stiffness or rigidity))).clm.	US - PGPUB	2007/0 9/06 17:55			